
VELCUT FLOCK — APPLICATION INSTRUCTIONS



Garment Care: wash & dry garment inside out, machine wash & dry at low temperatures, see specification, "Wash Resistance" use mild detergents, No Chlorine, Do not dry clean Flex; Flock OK, wait 24 hours before first washing.

Store SEF Heat Transfer Materials in a cool and dry place; protect against the influence of light when stored. We recommend not to exceed a storage period of 24 months. Due to the variety of possible influences / exposure outside of our control, to include processing / use, all specifications should be viewed as reference values. We recommend a suitability test to the material before a production. Technical specifications rest on extensive tests and technical research, however, a legally binding warranty of specific characteristics and or performance cannot be provided.



SEF Americas 14476-201 Duval Place West Jacksonville, FL 32218 T 904-423-0211 T 1-844-720-9600 F 904-423-0899 www.SEFamericas.com sales@SEFamericas.com



Technical Support: Toll Free 1-844-720-9601 techsupport@SEFamericas.com

Technical Information
"Tips & Tricks"
http://SEFamericas.blogspot.com